

Message Text

CONFIDENTIAL

PAGE 01 PORT M 00316 020545Z
ACTION SY-05

INFO OCT-01 EA-10 NEA-10 ISO-00 OCPE-00 OC-06 CCO-00
FBOE-00 OCL-00 A-01 SYE-00 SSO-00 /033 W
-----084978 020549Z /65

O R 020330Z MAR 78
FM AMEMBASSY PORT MORESBY
TO AMEMBASSY WELLINGTON IMMEDIATE
AMEMBASSY MANILA IMMEDIATE
SECSTATE WASHDC IMMEDIATE 3103
INFO AMEMBASSY DACCA
AMEMBASSY CANBERRA
AMEMBASSY BANGKOK
AMCONSUL HONG KNONG

C O N F I D E N T I A L PORT MORESBY 0316

WELLINGTON FOR CRO, PSO; MANILA FOR RCO/ATO;
DEPT FOR A/SY/OPS/T, A/OC/PE, A/FBO; DACCA FOR OIC/RTC BAGNAL;
CANBERRA FOR RSO; BANGKOK FOR TSO; HONG KONG FOR RTC/RSS
FROM TSO CANBERRA

E.O. 11652: XGDS-2
TAGS: ASEC, AFAC, ABLD
SUBJECT: CCC INSTALLATION AND REPAIR WORK

REF: A) STATE 050566, B) WELLINGTON 1019 (NOTAL),
C) CANBERRA 01491 (NOTAL)

1. FOR DEPT. IN ACCORDANCE REF A, TSO AND SEABEE CANBERRA
WILL PERFORM FAN COIL REPLACEMENT; ALSO REF B ELECTRICAL
WORK IF WITHIN CAPABILITY (SEE PARA 3B BELOW).

2. FOR MANILA. TWO ALTERNATIVES APPEAR LIKELY FOR
RELOCATION. ONE: TAP ONTO PRESENT PLUMBING INSIDE
ENCLOSURE AND ROUTE COPPER SUPPLY, RETURN, AND CONDENSATE
LINES TO NEW LOCATION WITH LINES VISIBLE WITHIN
CONFIDENTIAL

CONFIDENTIAL

PAGE 02 PORT M 00316 020545Z

ENCLOSURE. TWO: MAKE ADDITIONAL ENCLOSURE
PENETRATIONS AT NEW LOCATION AND TAP INTO LINES OUTSIDE
ENCLOSURE BETWEEN ENCLOSURE AND CONTINUITY BREAK. NOTE
THAT EXISTING ENCLOSURE PENETRATIONS FOR F/C UNIT CANNOT
BE SEALED AS THOSE PENETRATIONS ALSO SUPPLY TCU F/C
UNIT. PLEASE REPLY (WITH INFO TO CANBERRA/SYDNEY)
PREFERABLE METHOD AND ANY ADDITIONAL REQUIREMENTS.

3. FOR WELLINGTON. PLEASE PROVIDE DETAILED RESPONSES TO FOLLOWING QUESTIONS.

A. HAS THE REF A TSF-081C UNIT BEEN RECEIVED AND IN POST'S HANDS. IF NOT, EXPECTED ETA? DO YOU HAVE TSF-081C SET-UP HANDBOOK?

B. PER REF B. PLEASE SPECIFY EXACTLY WHAT ELECTRICAL WORK IS REQUIRED, TO DETERMINE NOT ONLY PARTS REQUIREMENTS BUT JOB TIME PLANNING.

C. TSO AWARE OF VIP TIME SCHEDULE AND TEMPERATURE PROBLEMS AND ASSUMING POST RECEIVES EQUIPMENT AND NECESSARY SUPPLIES, SEE NO PROBLEMS IN COMPLETING WORK PRIOR TO VISIT.

D. PER REF B. FAN COIL UNIT FOR ACR ROOM (RM 228) MAY BE INSTALLED BY CONTRACTOR. FYI. HIS ORIGINAL PROPOSAL INCLUDED THIS INSTALLATION COST. HOWEVER IF TIME PERMITS TEAM WILL ALSO INSTALL. END FYI.

E. CAN POST ACQUIRE 3/4" HARD DRAWN COPPER TUBING AND ASSORTED CONNECTORS (I.E. ELBOWS, T'S ETC) IN SHORT TIME FRAME? IF NOT, RECOMMEND POST START PROCUREMENT OF APPROXIMATELY 80 (EIGHTY) FEET OF COPPER TUBING, 15 ELBOWS, 3 T CONNECTORS AND 80 FEET INSULATION, THIS ASSUMES UNIT WILL BE LOCATED MAXIMUM DISTANCE FROM PRESENT LOCATION.

F. CAN POST HIRE PORTABLE TORCH (PROPANE) AND BOTTLE GAS SUPPLY?

CONFIDENTIAL

CONFIDENTIAL

PAGE 03 PORT M 00316 020545Z

4. FOLLOWING IS TSO CANBERRA PRESENT SCHEDULE:
REMAIN PORT MORESBY UNTIL 1430 ON 6 MAR, SYDNEY 6 AND 7 MAR, RETURN CANBERRA EVENING 7 MAR. TEAM WILL TENTATIVELY PLAN ARRIVAL FOR WELLINGTON ON OR AFTER 13 MAR IF POST IN RECEIPT OF UNIT AND ANY ASSOCIATED EQUIPMENT. WILL PROVIDE FIRM SCHEDULE UPON RESPONSE TO ABOVE QUESTIONS.
OLMSTED

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 02 mar 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978PORTM00316
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: X2
Errors: N/A
Expiration:
Film Number: D780095-0122
Format: TEL
From: PORT MORESBY
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t197803114/aaaadtat.tel
Line Count: 103
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: d5d9bab9-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: 78 STATE 50566, 78 WELLINGTON 1019
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 02 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 3140559
Secure: OPEN
Status: NATIVE
Subject: CCC INSTALLATION AND REPAIR WORK
TAGS: ASEC, AFAC, ABLD
To: WELLINGTON MANILA
Type: TE
vdkgvwkey: odbc://SAS/SAS.dbo.SAS_Docs/d5d9bab9-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014